## Labcorp Oklahoma, Inc. Test Directory

## **Acid Fast Stain**

Order Name: C AF ST
Test Number: 6200101
Revision Date: 10/28/2011

TEST NAME		1	METHODOLOGY	LOINC CODE	
Acid Fast Stain			Microscopy		
SPECIMEN REQUIREMENTS					
Specimen	Specimen Volume (min)	Specimen Type	Specimen Container	Transport Environment	
Preferred	5 mL (3)	Slide	See Instructions	Room Temperature	
Alternate 1	5 mL (3)	Respiratory specimen	Sputum Collection Container	Room Temperature	
Instructions	Make a slide from material to I	Make a slide from material to be stained, place into protected slide holder. Make sure slide is labeled with patient information and source material.			

GENERAL INFORMATION		
Testing Schedule	Daily	
Expected TAT	2 Days	
Clinical Use	Fluorescent stain to detect presence of Mycobacteria sp.	
CPT Code(s)	87206	
Lab Section	Microbiology	

Service provided by Labcorp Oklahoma, Inc. All Rights Reserved. © 2003 - 2024